

December 23, 2022

Don Kehn Don Kehn Construction, Inc. 6550 S. CR 5 Fort Collins, CO 80528

RE: Timnath Pit (Permit No. M-1989-056) Annual Groundwater Reports

Dear Mr. Kehn:

The ground water monitoring data for 2022 was submitted to the Division of Reclamation, Mining and Safety on December 7, 2022. The Division finished its review of the submitted data and has the following questions:

- 1. The data shows the quarterly water levels for 3 different wells but does not identify the well associated with each data set. Please update the monitoring report to identify the well associated with each data set.
- 2. A map showing the locations of the wells was submitted to the Division in September 1994 but does not identify each well. Please submit an updated map showing the well locations and identity of each well. The well identity needs to correspond with the quarterly water level data.

The following 2 issues were raised in the April 8, 2020 letter to Kehn Construction. These issues have not been resolved and need to be addressed:

- 1. A commitment was made by Don Kehn Construction in September 1994 to monitor the water level in 3 monitoring wells quarterly and submit the monitoring reports to DRMS on an annual basis. A review of the annual reports shows that the well monitoring data has not been submitted to the Division for 2017 through 2021. Please submit the well monitoring date for these years.
- 2. The last Substitute Water Supply plan for the Timnath Pit that the Division has on record expired on February 29, 2020. Please submit a copy of the most recent SWSP.

The above requested information are required commitments of the Timnath Pit Permit No. M-1989-056. The information needs to be submitted to the Division within 30 days of this letter to remain in compliance with the permit.



Don Kehn Construction, Inc. Page 2 of 2 December 23, 2022

If you have any questions, please contact me at (720) 774-0040 or brock.bowles@state.co.us.

Sincerely,

Brak Sands

Brock Bowles Environmental Protection Specialist

CC: Jared Ebert, DRMS Patrick Lennberg, DRMS



STATE OF COLORADO Bowles - DNR, Brock <brock.bowles@state.co.us>

Adequacy review of ground water data

1 message

Bowles - DNR, Brock <brock.bowles@state.co.us>

Fri, Dec 23, 2022 at 5:25 PM

To: Deb Kehn <deb@kehnconstruction.com>, accounting@kehnconstruction.com

Mr. Kehn,

The Division finished its review of the ground water data submitted for the Timnath Pit, M-1989-056 on December 7. Please see the attached file for follow up questions. Please note there is a 30-day requirement to remain in compliance with the permit. Brock

Brock Bowles Environmental Protection Specialist



COLORADO

Division of Reclamation, Mining and Safety

Department of Natural Resources

P 720.774.0040 | O 303.866.3567

Physical: 1313 Sherman St., Room 215, Denver, CO 80203 Mailing: Room 215, 1001 E 62nd Ave, Denver, CO 80216 brock.bowles@state.co.us | https://drms.colorado.gov

