

January 12, 2023

Tony Tennyson Elk Ridge Mining and Reclamation, LLC P.O. Box 628 27646 West 5th Avenue Nucla, CO 81424

## RE: New Horizon Mine Mine, Permit No. C-1981-008 2<sup>nd</sup> Quarter 2022 Sediment Pond Inspection Report / 2022 Annual Impoundment Inspection Report

Dear Mr. Tennyson,

The Division of Reclamation, Mining and Safety (the Division) has reviewed the Sediment Pond Inspection Report for the 2<sup>nd</sup> Quarter of 2022 and the Annual Impoundment Inspection Report for 2022. The report was received on June 27, 2022. The Division finds the report to be in compliance with the following Rules:

**4.05.9(14)(a)** – Annual inspections of the impoundments occurred during the  $2^{nd}$  quarter of 2022.

**4.05.9(14)(b)** – The reports were certified by a professional registered engineer that the impoundments have been maintained as designed, and in accordance with the approved plans.

**4.05.9(14)(c)** – Copies of the certified reports are retained at the mine site.

**4.05.9(15)(a)** – No indications of seepage, erosion or animal burrows were identified in the  $2^{nd}$  quarter. Spillways for the ponds were noted to be in good repair and functional.

**4.05.9(15)(b)** – The existing required monitoring procedures were met.

4.05.9(15)(c) - The amount of water impounded in the ponds was documented in the report.

4.05.9(15)(d) – The existing storage capacity of the impoundments was documented in the report.

**4.05.9(15)(e)** – The  $2^{nd}$  quarter report did not list any other aspects of the structure affecting stability, or requiring maintenance.

**4.05.9(17)** – All impoundments are inspected quarterly, by a qualified person designated by the operator, for the appearance of structural weakness and other hazardous conditions. The reports are retained at the New Horizon Mine, and copies of the reports are submitted to the Division on a quarterly basis.



1/12/2023 Page 2 of 2

During the 2<sup>nd</sup> quarter Pond 013 discharged.

This concludes the Division's review of the Sediment Pond Inspection Report for the 2<sup>nd</sup> Quarter of 2022 and the Annual Impoundment Inspection Report for 2022. If you have any questions, please contact me at (303)-866-3567 x8185 or clayton.wein@state.co.us.

Sincerely,

Clayton Wein

Clayton Wein Environmental Protection Specialist <u>clayton.wein@state.co.us</u>

cc: Travis Marshal, Senior Environmental Protection Specialist