




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Sharp Gravel Pit	MINE/PROSPECTING ID#: M-2012-036	MINERAL: Aggregate	COUNTY: Bent
INSPECTION TYPE: Monitoring	WEATHER: Clear, chilly	INSP. DATE: December 14, 2022	INSP. TIME: 10:30
OPERATOR: All-Rite Paving & Redi-Mix, Inc.	OPERATOR REPRESENTATIVE: Jodi Schreiber	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$60,000.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Nikie Gagnon	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: January 12, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION-- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Nikie Gagnon of the Division of Reclamation, Mining and Safety (Division). Jodi Schreiber representing All-Rite Paving & Redi Mix was present for the inspection. The Sharp Gravel Pit is located 0.5 mile west of Hasty on County Rd JJ. This inspection was carried out as a part of the Division's routine monitoring inspection program. At the time of the inspection it was clear and chilly, snow was on the ground.

Gen. Compliance With Mine Plan:

The site is a 112c operation with 320 acres permitted and the post-mining land use is rangeland. The approved maximum disturbance at any time is 27 acres. No mining activities have begun at the site. The permit area consists of undisturbed rangeland. Nothing in the Construction Materials Act and Rules requires operations to commence within a specified timeframe after permit approval. As long as the land is undisturbed by the operation, Rule 3.1.3 regarding time limit and phased reclamation (complete reclamation within 5 years of mining) does not apply.

Signs and Markers:

A permit sign was posted at the main site entrance off of Co Rd JJ. The rectangular shaped permit boundary was delineated by a property fenceline (4 strand barbed wire fence).

Financial Warranty:

The Division holds a \$60,000 bond for the site. The financial warranty was reviewed as a part of the inspection and the Division has determined the bond is adequate. The mining plan is split into two phases, Phase 1A (27 acres) and Phase 1B (43 acres). The current bond covers disturbance of Phase 1A. Prior to moving into Phase 1B, the operator would need to submit a Technical Revision to increase the maximum allowed disturbance and the required financial warranty for the operation will be reassessed.

Photographs taken during inspection are attached.

Please contact Nikie Gagnon (303)866-3567 ext. 8126 or email at nikie.gagnon@state.co.us if you have any questions regarding this report.

PHOTOGRAPHS





Inspection Contact Address

Jodi Schreiber
All-Rite Paving & Redi-Mix, Inc.
P.O. Box 165
Canon City, CO 81215

CC: Amy Eschberger, Senior EPS, DRMS