



January 25, 2023

Tony Tennyson
Elk Ridge Mining and
Reclamation, LLC
P.O. Box 628
27646 West 5th Avenue
Nucla, CO 81424

**RE: New Horizon North Mine, Permit No. C-2010-089
1st Quarter 2022 Discharge Monitoring Reports Review**

Dear Tony,

The Colorado Division of Reclamation, Mining and Safety (the Division) has finished reviewing the 2022 1st Quarter Discharge Monitoring Reports (DMRs). The reports were received on May 2, 2022. The Division finds the reports to be in compliance with the following Rules:

- **Rule 4.05.13(2)(i)** – Samples are measured accurately and record the quality and quantity of the water discharged from the permit area.
- **Rule 4.05.13(2)(ii)** – There are three outfalls associated with the COG850062 permit; Outfall 001, Outfall 002 and Outfall 003. During the months of January, February and March Outfalls 001 and 0002 did not discharge. Therefore, no exceedances occurred. Outfall 003 has not yet been constructed.
- **Rule 4.05.13(2)(iii)** – Discharge Monitoring Reports are received on a quarterly basis and filed with the Division within 90 days of the sample collection.

This concludes the Division's review of the 2022 1st Quarter Discharge Monitoring Reports. If you have any questions, please contact me at (303)-866-3567 x8185.

Sincerely,

Clayton Wein
Environmental Protection Specialist
clayton.wein@state.co.us



cc: Travis Marshal, Senior Environmental Protection Specialist