




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Thompson Pit	MINE/PROSPECTING ID#: M-2022-046	MINERAL: Sand and gravel	COUNTY: Montrose
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: February 9, 2023	INSP. TIME: 11:00
OPERATOR: Montrose County	OPERATOR REPRESENTATIVE: Brandon Wallace	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Pre-operation Inspection	BOND CALCULATION TYPE:	BOND AMOUNT: No Bond Held	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: February 14, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a pre-operation inspection conducted as part of the Division's normal review process for 112c applications. Brandon Wallace, representing the Operator, was present. Photographs are included with this report in order to illustrate the conditions observed.

The Thompson Pit is located approximately two miles southwest of Olathe and accessed from 57.50 Road, through the Neal Pit (M-1983-148).

Adequate notice of the application was posted at the entrance to the site.

The proposed affected area currently consists of a mixture of rangeland and pastureland. The post-mining land use will be the same as the pre-mining land use.

This inspection confirmed that conditions at the site are consistent with those represented in the application. No problems or violations were noted.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.



Inspection Contact Address

Keith Laube
Montrose County
63160 LaSalle Rd
Montrose, CO 81401