



N-1980-244 Notice of Water Quality Parameter Exceedance

1 message

Antonio Matarrese <Antonio.Matarrese@newmont.com>

Tue, Mar 14, 2023 at 10:42 AM

To: Patrick Lennberg - DNR <patrick.lennberg@state.co.us>

Cc: "Russell - DNR, Elliott" <elliott.russell@state.co.us>, Michael Cunningham <michaela.cunningham@state.co.us>, Katie Blake <Katie.Blake@newmont.com>, Johnna Gonzalez <Johnna.Gonzalez@newmont.com>, Ronald Parratt <Ronald.Parratt@newmont.com>, Paulina Barela <Paulina.Barela@newmont.com>, Norma Townley <Norma.Townley2@newmont.com>

Good Morning Patrick –

Please see CC&V's attached notice of water quality parameter exceedances. If you have any questions please contact me at Antonio.Matarrese@Newmont.com.

Best Regards,

Tony



Antonio Matarrese

ENVIRONMENTAL COORDINATOR

100 North 3rd Street

Victor, Colorado 80860

(719) 851-4185

(719) 250-3452

[NEWMONT.COM](http://newmont.com)



03142023 M-1980-244 NWQAPE.pdf

242K



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

March 14, 2023

SENT VIA EMAIL

Mr. Patrick Lennberg
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining, and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedance March 14, 2023

Dear Mr. Lennberg,

In accordance with Rule 3, Section 3.1.7 (9) of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining, and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected first quarter compliance groundwater samples from monitoring wells CRMW-3A, CRMW-3B, and CRMW-3C on February 20, 2023.

Upon review of received analytical reports, CC&V determined monitoring well CRMW-3A exceeded established numeric protection levels for Fluoride and the table value standard for Sulfate. Monitoring well CRMW-3B exceeded the established numeric protection level for Fluoride. Monitoring well CRMW-3C exceeded the established numeric protection level for Fluoride and Manganese and the table value standard for Sulfate.

Table 1 below lists these exceedances by the location and the associated parameter. The graphs contained in Attachment A demonstrate the parameter trend for the collected data.



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860


P 719.689.2977
F 719.689.3254
newmont.com

Table 1: Parameter Values

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Value Standard (mg/L)
CRMW-3A	2/20/2023	Fluoride	3.07	2	2
CRMW-3A	2/20/2023	Sulfate	1100	250	250
CRMW-3B	2/20/2023	Fluoride	3.33	2	2
CRMW-3C	2/20/2023	Fluoride	2.99	2	2
CRMW-3C	2/20/2023	Manganese	3.82	3	0.05
CRMW-3C	2/20/2023	Sulfate	842	250	250

Should you require further information please do not hesitate to contact Antonio Matarrese at 719.851.4185 or Antonio.Matarrese@Newmont.com or myself at 719.851.4048 or Katie.Blake@Newmont.com

Sincerely,

DocuSigned by:

5A3D013B629844B...

Katie Blake

Sustainability & External Relations Manager
Cripple Creek and Victor Gold Mining Company

EC: P. Lennberg
E. Russell
M. Cunningham
K. Blake
J. Gonzalez
R. Parratt
P. Barela
N. Townley



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

Attachment A

