

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 2 (south side) - Looking East along N side of CR 32.5



Close-up of markers

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 2 (south-east side) - Looking South toward CR 32.5, with South Platte River off photo to left. Right photo taken from farther north.

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 2 (south-east side) - Looking north, with South Platte River off to right side. Right photo taken from farther north into Phase 2.

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 2 (south side) - Looking west along N side of CR 32.5



Phase 3 (south side) - Looking east along N side of CR 32.5

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 3 (south side) - Looking west along N side of CR 32.5



Phase 3 (west side) - Looking south along E side of CR 21

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 3 (west side) - Looking north along E side of CR 21



Close-up of marker near NW corner of Phase 3

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 3 (north side) - Looking east toward South Platte River



Phase 3 (north side) - Looking southeast, on edge of terrace, with CR 32.5 in distance by red building, and CR 21 off to right

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 3 (north side) - Looking east and downhill from edge of terrace toward irrigation return flow ditch, and across ditch to Phase 2. (South Platte River is off photo to left.) Right photo looking east across ditch - can see Phase 2 markers on far side of ditch.

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 3 (south side) - Looking east along N side of CR 32.5



Phase 4 (north side) - Looking east along S side of CR 32.5

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 4 (southwest corner) - Looking east, close-up of marker near SW corner of Phase 4.



Phase 4 (west side) - Looking north along E side of CR 21

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 1 (north side) - Looking east along S side of CR 32.5



Phase 1 (north side) - Looking south along E side of shop fence

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 1 (north side) - Looking west along S side of CR 32.5



Phase 1 (north side) - Looking east along S side of CR 32.5

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 1 (east side) - Looking north toward CR 32.5 with South Platte River on right. Right photo - another marker on east side of Phase 1.

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 1 (east side) - Looking south with South Platte River on left.



Phase 1 (south side) - Looking west from near SE corner of phase.

WEST FARM - DRMS Permit M-2022-048 - mine permit boundary markers (photos 03/08/23)

Mine Permit Boundary marked to comply with Corrective Action noted in DRMS Inspection Report (12/22/22)



Phase 1 (northeast side) - Looking east toward South Platte River, with CR 32.5 on left.