




FIGURES






















Figure 7. Logan Wash Mine 2022 Precipitation





440 110 220 Feet 1:3,037 P. debilis in the roadways or bar ditches will be either translocated or protected with matting. Lower Bench Road Upper Bench Road BLM affected area Source: Esri, DigitalGlobe, GeoEye, Earthster Geographics, CNE USDA, USCS, AeroGRID, IGN, and the GIS User Community Legend Figure 10. Locations of P. debilis, Proposed 2015 P. debilis Potentially disturbed area **Mitigation measures and Potential Transplant** (Location+/- 10 feet) Areas Potential transplant area 2019 P. debilis survey ıh CNAP boundary Protective barricade wwi or matting Western Water & Land, Inc. Garfield County, Colorado Bureau of Land Management Applications in Earth Science (USBLM) parcels

