



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

April 9, 2023

Daniel Takami
Grand Island Resources LLC
12567 West Cedar Dr.
Lakewood, CO 80228

Re: Division Comment, Fourth (4th) Quarter 2022 Groundwater and Surface Water Monitoring Report; Cross Gold Mine, Permit No. M-1977-410

Dear Mr. Takami,

On April 7, 2023, the Division of Reclamation, Mining and Safety (Division/DRMS) received your responses to the Division's request for additional information, dated March 2, 2023, for the 4th Quarter 2022 Groundwater and Surface Water Monitoring Report for the Cross Gold Mine. After review of the submission the Division has the following comment.

At this time the Division does not consider the 4th Quarter 2022 monitoring data to qualify as one quarter of baseline monitoring because not all of the data was collected in a manner consistent with the approved methods described in TR-10.

If you have any questions or need further information, please contact me at (303) 866-3567 x8114, or by email at patrick.lennberg@state.co.us.

Sincerely,

Patrick Lennberg
Environmental Protection Specialist

cc: Jared Ebert; DRMS

ec: Daniel Takami, danieltakami@gmail.com, Grand Island Resources LLC
Sergio Rivera, sergio.rivera@novametallix.com, Grand Island Resources LLC

