

# ANNUAL & QUARTERLY POND INSPECTION

## COORS ENERGY COMPANY

### KEENESBURG MINE SITE

Date of Inspection 2/8/2023

Pond Identification:		<b>Sediment Pond #2</b>		<b>Dugout</b>	
Type of Pond		Sediment		Permanent	
<b>Capacities</b>		15.6 acre ft. 5,097,925 gals.		19.7 acre ft. 6,437,760 gals.	
Approx. water level - (% of capacity)		Trace/snow		Trace/snow	
Sediment level - (% of capacity)		0		0	
Out flow					
<b>Erosional Features</b>		yes - no		yes - no	
Rills / Gullies		No		No	
Inadequate Vegetation		No		No	
Outlet Channel Erosion		No		No	
Burrows		No		No	
Other		NA		NA	
<b>Structural Issues</b>					
Settlement		No		No	
Cracks/Slides		No		No	
Seepage		None		None	
Spillways (cond.)		Good		Good	
Other		NA		NA	

Signature (P.E. or Authorized Inspector): Ben Moline, PE

