



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

May 4, 2023

SENT VIA EMAIL

Mr. Patrick Lennberg
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining, and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedance May 4, 2023

Dear Mr. Lennberg,

In accordance with Rule 3, Section 3.1.7 (9) of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining, and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected second quarter compliance groundwater samples from monitoring wells GVMW-8A on April 10, 2023 and from SGMW-6B on April 12, 2023.

Upon review of received analytical reports, CC&V determined monitoring well GVMW-8A exceeded established numeric protection levels for fluoride. Monitoring well SGMW-6B exceeded established numeric protection levels for Fluoride, Iron, and Manganese and exceeded table value standards for Beryllium and Sulfate.

Table 1 below lists these exceedances by the location and the associated parameter. The graphs contained in Attachment A demonstrate the parameter trend for the collected data.

Table 1: Parameter Values

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Value Standard (mg/L)
GVMW-8A	4/10/2023	Fluoride	2.62	2	2
SGMW-6B	4/12/2023	Beryllium	0.0628	0.004	0.004
SGMW-6B	4/12/2023	Fluoride	7.48	2	2
SGMW-6B	4/12/2023	Iron	14.4	14	0.3
SGMW-6B	4/12/2023	Manganese	8.75	3	0.05
SGMW-6B	4/12/2023	Sulfate	1220	250	250



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

Should you require further information please do not hesitate to contact Antonio Matarrese at 719.851.4185 or Antonio.Matarrese@Newmont.com or myself at 719.851.4048 or Katie.Blake@Newmont.com

Sincerely,

DocuSigned by:

5A3D013B629844B...

Katie Blake

Sustainability & External Relations Manager
Cripple Creek and Victor Gold Mining Company

EC: P. Lennberg
E. Russell
K. Blake
P. Barela
N. Townley

File: "C:\Users\19012214\Newmont USA Limited\CC&V - S&ER Environmental - Environmental Compliance\Water\DRMS\Exceedance Notifications\2023 - Q2\May 4, 2023\Final Notification"



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

Attachment A











