

2023 DRMS Annual Report

Rocky Mountain Materials - Red Canyon Quarry
M-1985-043

Legend

- Area of Reclamation
- Disturbed Area
- Reclamation Soil Stockpile

Red Canyon Quarry

Disturbance Boundary

Mining Permit Boundary

Disturbed Area

Reclamation Soil Stockpile Area

~ 1.1 Acres Re-seeded Spring 2022

Area undergoing active revegetation

~1.1 Acres - Disturbed in 2021

Google Earth

Image © 2023 Maxar Technologies

2000 ft