



CRIPPLE CREEK & VICTOR

newmont.com

PO Box 191
100 N. 3rd Street
Victor CO 80860

June 20, 2023

ELECTRONIC DELIVERY

Mr. Elliott Russell
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company; Cresson Project;
March 13, 2023 Inspection Corrective Action Due Date Extension Request

Dear Mr. Russell:

On March 13, 2023, Colorado Division of Reclamation, Mining, and Safety (the Division) completed a routine monthly inspection, accompanied by representatives of Newmont Corporation's Cripple Creek and Victor Mining Company (CC&V). The inspection report date of April 21, 2023, issued to CC&V by the Division requires a report detailing the Carlton Tunnel pond clean out process and characterization of the material in the pond to be submitted by June 20, 2023.

CC&V hereby requests an extension to the corrective action due date from June 20, 2023 to June 29, 2023.

Should you require further information, please do not hesitate to contact Johnna Gonzalez at (719) 313-0447, Johnna.Gonzalez@Newmont.com, or myself at Katie.Blake@newmont.com.

Sincerely,

DocuSigned by:

5A3D013B629844B...

Katie Blake
Sustainability & External Relations Manager
Cripple Creek & Victor Gold Mining Co

EC:

M. Cunningham – DRMS
N. Gagnon – DRMS
D. Swallow – Teller County
J. Gonzalez – CC&V
A. Matarrese – CC&V
K. Blake – CC&V
N. Townley – CC&V