



STATE OF
COLORADO

Simmons - DNR, Leigh <leigh.simmons@state.co.us>

C1983059, Terror Creek Loadout, July Inspection Report

1 message

Simmons - DNR, Leigh <leigh.simmons@state.co.us>
To: Doug Smith <Doug.Smith@oxbow.com>

Fri, Jul 14, 2023 at 3:00 PM

Attached

Leigh Simmons
Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 x 8121 | C 720.220.1180 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
leigh.simmons@state.co.us | <https://drms.colorado.gov>




INSP-REPORTC_C1983059_LDS_07142023025352.pdf
559K



PERMIT INFORMATION

Permit Number: C-1983-059 Mine Name: Terror Creek Loadout Operator: Oxbow Mining, LLC Operator Address: Mr Doug Smith PO Box 535 Paonia, CO 81434	County: Delta Operation Type: Loadout Permit Status: Active Ownership: Private
	Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: July 12, 2023 Inspection Start Time: 13:00 Inspection End Date: Inspection End Time:	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Leigh Simmons	Inspector's Signature:  Signature Date: July 14, 2023

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Roads

N - Availability of Records

N - Reclamation Success

N - Backfill & Grading

N - Revegetation

N - Excess Spoil and Dev. Waste

N - Subsidence

N - Explosives

N - Slides and Other Damage

N - Fish & Wildlife

N - Support Facilities On-site

N - Hydrologic Balance

N - Signs and Markers

R - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

N - Processing Waste

N - Topsoil

COMMENTS

This was a partial inspection by Leigh Simmons of the Division of Reclamation, Mining and Safety (Division). The weather was hot, clear and dry. There was no activity at the site, and no sign of any recent disturbance.

GENERAL MINE PLAN COMPLIANCE:

There had been no activity at the site since the last inspection. Work had not yet begun to prepare the pad for its future industrial/commercial use.

DOCUMENTS RECEIVED

N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 1Number of Complete Inspections this Fiscal Year: 0

PHOTOGRAPHS



Figure 1: Overview of pad

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 0