




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Sunbeam Pit #1	MINE/PROSPECTING ID#: M-2002-059	MINERAL: Sand and gravel	COUNTY: Moffat
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: July 26, 2023	INSP. TIME: 09:30
OPERATOR: Moffat County	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Zach Trujillo	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: August 7, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program by Zach Trujillo. The Sunbeam Pit #1 is a 112c permitted site. It is located approximately 5.5 miles northeast of Maybell and is accessed from Highway 318. No representative attended the inspection on behalf of the Moffat County but was notified prior.

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. Overburden and topsoil piles were also marked for designation and were vegetated. The entire permit boundary was inspected to ensure all disturbance was within the approved limits. No issues were observed.

The site was inactive at the time of the inspection. No equipment or fuel was observed on site. Several gravel stockpiles were observed on site within the pit boundary. All of which are stable with no erosion. The pit is has been excavated to a depth of approximately 15 feet, with slopes no steeper than 3H:1V.

This pit is operated by a government entity therefore no bond is required. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Zach Trujillo at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 or via email at zach.trujillo@state.co.us

PHOTOGRAPHS



Inspection Contact Address

None
Moffat County
PO Box 667
Craig, CO 81626

Enclosure

CC: Amy Eschberger