

MICA WHITE TENSION CRACK INSPECTION

Date	Highwall-Bench Stability	Active Slope	Highwall-Bench Height	Undercutting?	Tension Cracks?	Highwall Failures?	Inspected By Signature	If Issues, Resolution Timeframe	Resolution Date
2/24/23	Stable	No Movement	40'	No	Stable	No	BT		
3/1	"	"	"	"	"	"	BT		
3/8	"	"	"	"	"	"	BT		
3/15	"	"	"	"	"	No	BT		
3/23	"	"	"	"	"	No	BT		
3/31	Good	"	"	"	"	"	BT		
4/17	"	"	"	"	"	"	BT		
4/14	"	"	"	"	"	"	BT		
4/21	No Movement	"	"	No	"	No	BT		
4/27	"	"	"	"	"	No	BT		
5/8/23	Stable	"	"	No	No Movement	"	BT		
5/16	"	"	"	"	"	"	BT		
5/22	"	"	"	"	"	"	BT		
5/31	Good	No	40'±	No	No Movement	"	BT		
6/14	"	"	"	"	"	"	BT		
6/15	"	"	"	"	"	"	BT		
6/23	"	"	"	"	"	"	BT		
6/29	"	"	"	"	"	"	BT		
7/7/23	Good	No Movement	40'±	No	No Movement	"	BT		
7/17	"	"	"	"	"	"	BT		
7/25	"	"	"	"	"	"	BT		