




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Clay Pit No. 21	MINE/PROSPECTING ID#: M-2009-060	MINERAL: Clay (general)	COUNTY: Moffat
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: July 26, 2023	INSP. TIME: 11:00
OPERATOR: Moffat County	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Zach Trujillo	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: August 7, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program by Zach Trujillo. The Clay Pit No. 21 is a 112c permitted site that includes a total of 18.5 permitted acres. It is located approximately 20 miles northwest of Maybell, CO and is accessed from Moffat County Road 20. This site is on Bureau of Land Management (BLM) land however they were not present for the inspection. No representative for Moffat County was present.

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. The sign is located at the entrance of the permit boundary. T-posts have been placed to clearly delineate permit boundaries as well as a wire fence along the county road.

The site was inactive at the time of the inspection. One small material stockpile was located within the pit. No equipment or fuel is stored on site during the inspection.

The topsoil pile is located on the western side of the mine. The topsoil and overburden piles are clearly marked for designation. The topsoil pile was vegetated however limited coverage was present. No major erosion was observed on site. All slopes within the pit have been graded to approximately 3H: 1V or less.

This pit is operated by a government entity therefore no bond is required. No problems or violations were noted during this inspection.

PHOTOGRAPHS









Inspection Contact Address

None
Moffat County
PO Box 667
Craig, CO 81626

Enclosure

CC: Amy Eschberger