### **DRMS Minerals Revision Application Modification**



Department of Natural Resources

# Login

#### **General Information**

Permit Number \*

M1977493

Select Revision \*

If there are no options available it's because there are no open revisions of the selected type for the selected permit number

5-Dam Seepwater Collection Area, Secondary Containment System-EPF

**Operation Name** 

Revision Application Form Selection \*

TR - Technical Revision

Revision Sequence \*

If this does not populate, please contact your specialist to determine which sequence number to use.

30

The following pages will show the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information. Indicating that it is inaccurate will send an email to notify your administrator to make the appropriate changes.

### **Contact Information**

#### **Permittee Contact Information**

**Permittee Name** 

Climax Molybdenum Company

**Permittee Contact** 

Eric Detmer

**Permittee Address 1** 

Highway 91, Fremont Pass

**Permittee Address 2** 

**Permittee City** 

**Permittee State** 

**Permittee Zip Code** 

Climax

CO

804290000

**Permittee Contact Email Address** 

edetmer@fmi.com

**Permittee Contact Phone Number** 

### **Permitting Contact Info**

**Permitting Name** 

Climax Molybdenum Company

**Permitting Contact** 

James Davis

**Permitting Address 1** 

Hwy 91 - Fremont Pass

**Permitting Address 2** 

**Permitting City** 

**Permitting State** 

**Permitting Zip Code** 

Climax

CO

804290000

**Permitting Contact Email Address** 

**Permitting Contact Phone Number** 

7194862150

# **Inspection Contact Info**

**Inspection Name** 

Climax Molybdenum Company, Climax Mine

**Inspection Contact** 

Eric Detmer

**Inspection Address 1** 

Highway 91, Fremont Pass

Inspection Address 2					
Inspection City Climax	<b>Inspection State</b> CO	Inspection Zip Code 804290000			
Inspection Contact Email Address edetmer@fmi.com					
Inspection Contact Phone Number 7194867633					
Is the contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *					
Yes O No					
Once this form is submitted you	ı will see a link to update contact i	nformation, which you may do if you're an admin.			

# Surface Area Changes

#### **Revision**

Revision Title \* (?)

5-Dam Seepwater Collection Area, Secondary Contain

Short description

Narrative Description of Revision \* (?)

Technical Revision (TR) 36 describes plans to construct a secondary containment system to capture and pump back potential overflow or release from Climax's Mayflower Seepage Collection and Clear Ponds. This system will collect, contain and route Mayflower TSF seepage back into the seepage system. N

Detailed description used for notifications

#### **Bond Amount Change?** \*

O Yes 

No

#### Additional Surface Disturbance? \*

O Yes 

No

# **Proposed Acreage Revisions**

#### Permit Area

Current Value	Proposed Change Value * (?)	Calculated Revised Total
14000.00	0.00	14000.00
		This value must equal the total of all Surface and

### Affected Area

Current Value	Proposed Change Value * (?)	Calculated Revised Total
7908.00	0.00	7908.00

# Attachments & Maps

**Public Notice / Proof of Posting Attachment** 

Do you have attachments? \*

• Yes • No

### **Attachments**

Standard Uploads

**Document, NOT Confidential** 

Map, NOT Confidential 10.72MB

Proof of Publication

TR-36 submittal 091323.pdf

**Confidential Uploads** 

**CONFIDENTIAL Document** 

**CONFIDENTIAL Map** 

### **Signature**

**Date** 

09/13/23

By checking this box you have thoroughly reviewed this Mineral Revision form and are ready to submit this form to DRMS.

I Agree