

## WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME: 3/23/23

INSPECTOR SIGNATURE: Mianda Kaweah

INSPECTOR TITLE: Environmental Manager

This inspection was conducted to comply with DMG Rule 4.09.1(11).

This inspection was conducted to evaluate:

☒ A. Stability of fill (quarterly inspection)

☐ B. Critical construction periods:

- ☐ 1. Removal of all organic material/topsoil
- ☐ 2. Placement of underdrainage system
- ☐ 3. Installation of surface drainage system
- ☐ 4. Placement and compaction of fill materials
- ☐ 5. Revegetation

NOTES:

Pile is still covered in snow. Very little  
run off has occurred, pile appears stable.  
This is the most snow the pile has had  
since reclamation. Will watch pile closely for  
erosion as snow begins to melt.