

WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME: 9/19/23

INSPECTOR SIGNATURE: Minanda Kawcak

INSPECTOR TITLE: Environmental Manager

This inspection was conducted to comply with DMG Rule 4.09.1(11).

This inspection was conducted to evaluate:

☒ A. Stability of fill (quarterly inspection)

☐ B. Critical construction periods:

☐ 1. Removal of all organic material/topsoil

☐ 2. Placement of underdrainage system

☐ 3. Installation of surface drainage system

☐ 4. Placement and compaction of fill materials

☐ 5. Revegetation

NOTES:

Refuse pile is stable and well vegetated.
Easterly side is a little weedy + sparse.
Overall pile is in good condition.