



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

DRMS Review of 2023 Williams Fork Refuse Pile and DMRs

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Nov 8, 2023 at 3:26 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good afternoon Miranda,

Please find DRMS's review of the above mentioned compliance reports for the Williams Fork mine.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 ext 8105 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

3 attachments



DMR_Review_2023_Q1_WF.pdf

215K



WastePile_Review__WF_2023.pdf

252K



DMR_Review_2023_Q3_WF.pdf

216K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

10 May 2023

Miranda Kawcak
Moffat County Mining, LLC
29515 Routt County Road #27
Oak Creek, CO 80467

RE: Williams Fork Mine Permit; C1981044
DRMS Review of 2023 Quarter 1 Discharge Monitoring Reports (DMRs)

Dear Ms. Kawcak:

Thank you for your submittal of the 2023 quarter one Discharge Monitoring Reports for the Williams Fork Mine. The Colorado Division of Reclamation, Mining and Safety (The Division), has reviewed the above referenced report. The reports were received by The Division on 2 May 2023. The reports cover the time frame of January 2023 through March 2023 (Q1), for discharge monitoring required by the discharge permit.

This report appears to comply with the applicable sections of Rule 4.05.13(2)(a)(iii).

No discharge from outfalls 003A, 022A, and 024A was recorded during quarter one.

No exceedances of water quality standards were identified in the Discharge Monitoring Report submitted.

The Division has no further comments at this time.

Best Regards,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II





COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

28 October 2023

Miranda Kawcak
Moffat County Mining, LLC
29515 Routt County Road #27
Oak Creek, CO 80467

RE: Williams Fork Mine Permit; C1981044
DRMS Review of 2023 Quarter 3 Discharge Monitoring Reports (DMRs)

Dear Ms. Kawcak:

Thank you for your submittal of the 2023 quarter three Discharge Monitoring Reports for the Williams Fork Mine. The Colorado Division of Reclamation, Mining and Safety (The Division), has reviewed the above referenced report. The reports were received by The Division on 27 October 2023. The reports cover the time frame of July 2023 through September 2023 (Q3), for discharge monitoring required by the discharge permit.

This report appears to comply with the applicable sections of Rule 4.05.13(2)(a)(iii).

Spoil Spring outfall 022A discharged during the quarter. The recorded total recoverable iron appeared outside the permitted limit. No discharge from the monitored outfalls 003A, and 024A was recorded during quarter three.

With the exception of the spoil spring, no exceedances of water quality standards were identified in the Discharge Monitoring Report submitted.

The Division has no further comments at this time.

Best Regards,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II

