

ANNUAL REPORT

Permit: M-2001-106

Operation Name: Orlando Pit

The portable crusher and associated equipment were in the site until September 2023. The equipment was staged within the northern boundary of the pit. Mining followed southwestern direction. A topsoil stockpile which was seeded is located on the northern portion of the permit boundary. To date no reclamation to the ground disturbance has been done. There will be one crushed gravel stockpile located close to the northern pit boundary.

This mining set was completed September 2023.