



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

January 12, 2024

Daniel Takami  
Grand Island Resources LLC  
12567 West Cedar Dr.  
Lakewood, CO 80228

**Re: Letter of Monitoring Compliance, Third Quarter 2023 Groundwater, Effluent and Surface Water Monitoring Report; Cross Gold Mine, Permit No. M-1977-410**

Dear Mr. Takami:

On December 29, 2023, the Division of Reclamation, Mining and Safety (Division/DRMS) received the Third Quarter 2023 Groundwater, Effluent, and Surface Water Monitoring Report for the Cross Gold Mine, permit no. M-1977-410. The Division did note on Figures 15, 16 and 17 a couple of the potentiometric lines are mislabeled with an additional "9" being added. However, the figures do not change with correct labelling so the Division is not requesting an update at this time. The Division has no additional comments on the report.

Please note that monitoring data is to be submitted quarterly in accordance with commitments made in TR-10.

If you need additional information or have any questions, please contact me by telephone at **303-866-3567 x8114**, or by email at [patrick.lennberg@state.co.us](mailto:patrick.lennberg@state.co.us).

Sincerely,

Patrick Lennberg  
Environmental Protection Specialist

cc: Jared Ebert, DRMS

ec: Daniel Takami, Grand Island Resources LLC, [danieltakami@gmail.com](mailto:danieltakami@gmail.com)

