



* Marked area indicates mining area. We plan to finish mining in these areas then reclaim the slope

Map 1: Inspection map generated for the December 12, 2023 inspection. The most recent Google Imagery is dated October 2020. Since the aerial image was taken, mining has progressed further south (yellow line) and south-east. The arrow points to the eastern highway that needs to be addressed.