## WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME:	11 15 2023
INSPECTOR SI	IGNATURE: Muanda Kawcak
INSPECTOR T	ITLE: Enviro Manager
This inspection	was conducted to comply with DMG Rule 4.09.1(11).
This inspection	was conducted to evaluate:
_ <b>/</b> _A	. Stability of fill (quarterly inspection)
B	. Critical construction periods:
	1. Removal of all organic material/topsoil
	2. Placement of underdrainage system
	3. Installation of surface drainage system
	4. Placement and compaction of fill materials
	5. Revegetation
NOTES:	Area is Stable. Vegetation Showed to be decent and progressing during 2023. Vegetation has began togo dormant for the season.