



Photo 1 Looking south from top of west end highwall



Photo 2 Looking north at western most end of highwall.



Photo 3 Reclaimed two track road and topsoil berm area on top of highwall



Photo 4 & 13 Looking west along crest of highwall.



Photo 6 Looking west at west end of reclaimed highwall



Photo 5 Looking west at east end of reclaimed highwall



Photo 9A Looking west. Sediment control basin and armored area.



Photo 9B Looking south across mine floor to the sediment basin and armored area.



Photo 7 Looking west at south facing slope below internal road.




Photo 8 Looking west at reclaimed sediment basin.



Photo 10 Looking north east across floor at old mine area..



Photo 12 looking west across equipment storage area.



Photo 14 Looking west, MSHA berm area on left, mine floor and slope on right.




Photo 15



Photo 16 MSHA berm location on right side and pit floor and south facing slope of mined area