


Note 1: NAIP 2019 Satellite Imagery

TOTAL MINING ACRES CURRENTLY AFFECTED: 19.03±  
MINING ACRES NEWLY AFFECTED: 0.97±  
NUMBER OF ACRES RECLAIMED: 0.00±  
APPROXIMATED NEW ACREAGE TO BE AFFECTED IN  
THE NEXT YEAR REPORT: 1.00±  
APPROXIMATED NEW ACREAGE TO BE RECLAIMED IN  
THE NEXT YEAR REPORT: 0.00±  
NO STRUCTURES WITHIN 25' OF PERMIT BOUNDARY



#### DRAWING LEGEND

	Pit Tract Boundary
	Existing Permit Boundary
	Section Line
	Edge of gravel roadway
	Fence line
	Entry
	Pin set by PLS 14840
	Section Monument (As Described)



**SUMMIT ENGINEERING CO.**  
ENGINEERS & LAND SURVEYORS  
P: 719-589-6147 F: 719-589-6633  
Loc: 1317 State Ave. Alamosa, CO 81101  
Mail: P.O. Box 1897 Alamosa, CO 81101  
www.summitengineering.co  
summitengco@gmail.com

**PROJECT**  
2021 Robins Consolidate Pit Annual Map  
5101 State Hwy. 285 Antonito, CO 81120  
Conejos County  
Owner: Robins Construction, LLLP

Job: 1707122CE Print Draft: A Date: 04-23-2021  
Designed By: ### Drawn By: KFA Checked By: SEJ

**SHEET NAME**  
Annual Map

**C-101**

SHEET NO. 1 OF 1