


- Main contours (50' interval)
- Intermediate contours (10' interval)
- Estimated contours (2' to 5' interval)
- Perennial Streams
- Ephemeral Drainages
- Fences
- Buildings
- Trees and/or Forest

- Primarily weeds with some grasses and forbs underneath, but with young cottonwood plants here and there south of the road. (24.2 acres)
- Vegetation severely affected by flooding; mainly weeds but also with desirable plants planted or brought in by flooding. (5.3 acres)
- Location of deep fill of foreign materials. No vegetation so fill likely done well after the growing season. (3.7 acres; about 42,000 cu yds assuming ave. depth = 7 feet)
- Low weed density and high grass success plus spotty facultative and obligate wetland species as well as sparse young willows and cottonwood. (6.1 acres)

Total affected land reclaimed = 43.3 acres



Miller Gravel Pit (M-1982-112)	
UPDATED: March 2024	2024 Annual Report Map Due: March 11, 2024
SCALE 1"=500'	
SHEET 1 of 2	Revegetation Status

Road Continues South
and then East