

STATE OF
COLORADO

Lennberg - DNR, Patrick <patrick.lennberg@state.co.us>

Additional Surface Water Monitoring Locations Required Letter, Grassy Valley, M1980-244

Joshua Adams <Joshua.Adams@newmont.com>


Mon, Mar 18, 2024 at 4:10 PM

To: "Lennberg - DNR, Patrick" <patrick.lennberg@state.co.us>, Norma Townley <Norma.Townley2@newmont.com>, Katie Blake <Katie.Blake@newmont.com>, Johnna Gonzalez <Johnna.Gonzalez@newmont.com>, Antonio Matarrese <Antonio.Matarrese@newmont.com>

Cc: Elliott Russell - DNR <elliott.russell@state.co.us>, Amy Eschberger - DNR <amy.eschberger@state.co.us>, Nikie Gagnon - DNR <nikie.gagnon@state.co.us>, Hunter Ridley - DNR <hunter.ridley@state.co.us>, "West - DNR, Lucas" <lucas.west@state.co.us>

Patrick,

As you may know, CC&V received a substantial amount of snow over the weekend. Prior to the most recent storm, it is estimated that the Grassy Valley surface water monitoring locations were buried in 2.5' of snow. Per the Community Collaborative Rain, Hail and Snow Network (see below screenshots) this most recent storm brought another 36.5" of snow. CC&V estimates that snow depth within Grassy Valley is more than 5' (from the reported snow totals and visual estimation) and attempting to monitor surface water locations poses a safety hazard for Newmont personnel. CC&V is diligently working to re-establish safe access to all monitoring locations and will continually monitor the conditions in Grassy Valley. CC&V will update DRMS when the surface water monitoring locations are once again accessible for inspection. Please let me know if you have additional questions. Thank you!



COMMUNITY COLLABORATIVE RAIN, HAIL & SNOW NETWORK
"Because every drop counts"

[Home](#) | [Countries](#) | [States](#) | [View Data](#) | [Maps](#) | [My Data Entry](#) | [Login](#)

[View Data](#)

- [Daily Precip Reports](#)
- [Daily Comments Reports](#)
- [Significant Weather Reports](#)
- [Multiple Day Reports](#)
- [Condition Monitoring Reports](#)
- [Condition Monitoring Charts](#)
- [Soil Moisture](#)
- [ET Reports](#)

[Days with Hail](#)
[Search Hail Reports](#)
[Station Hail Reports](#)
[Station Precip Summary](#)

[Water Year Summary](#)
[Station Precip Summary](#)
[Station Snow Summary](#)
[Rainy Days Report](#)
[Total Precip Summary](#)

[Station Water Balance](#)
[Water Balance Summary](#)
[Water Balance Charts](#)

[List Stations](#)

FROST Data

- [Frost](#)
- [Optics](#)
- [Snowflake](#)
- [Thunder](#)

View Data : Station Snow Report Summary US Units ▼

Station Report Summary

Station 1 : Example: CO-LR-273
Station 2 :
Station 3 :
Start Date: **End Date:**

Stations:
CO-TL-16
Cripple Creek 5.1 NW
Lat: 38.807053
Lon: -105.2310867
* indicates Multi-Day Accumulation Report

Station **CO-TL-16**

Date	Precip in.	24-hr Snowfall in.	24-hr Snowfall SWE in.	24-hr Snowfall SLR	Snowpack Depth in.	Snowpack SWE in.	Snowpack Density
03/13/2024	0.03	0.5	NA	NA	2.0	NA	NA
03/14/2024	1.90	27.0	NA	NA	28.0	NA	NA
03/15/2024	0.35	8.0	NA	NA	30.0	NA	NA
03/16/2024	0.08	T	NA	NA	28.0	NA	NA
03/17/2024	0.06	1.0	NA	NA	24.0	NA	NA
03/18/2024	T	T	NA	NA	20.0	NA	NA
Totals :	2.42 in.	36.5 in.	0.00 in.	--	--	--	--



Newmont
CRIPPLE CREEK & VICTOR

Josh Adams, PG

SITE WATER COORDINATOR

Cripple Creek & Victor Gold Mining Company

Victor, CO 80860

719.851.4260

719.323.0438

3/19/24, 4:49 AM

State.co.us Executive Branch Mail - Additional Surface Water Monitoring Locations Required Letter, Grassy Valley, M1980-244

[NEWMONT.COM](https://newmont.com)

[Quoted text hidden]