




PROJECT:
360100-002

TASK
-09

PREPARED BY:

TELESTO
SOLUTIONS INCORPORATED

DUNN PIT (M-2021-059) – Monitoring Well Locations

PREPARED FOR:



Dunn Pit (M-2021-059) Monitoring Wells Measurements: 2022-2023

Depth to Groundwater from Ground Surface

Date Measured	MW-01	MW-02	MW-03	MW-04	MW-05	MW-06	MW-07	MW-08	MW-09	MW-10
January-22	5.54	5.30	6.90	6.08	5.97	4.44	4.91	5.08	4.13	7.61
February-22	5.74	5.43	6.27	6.21	6.29	4.70	4.88	5.33	4.12	7.47
March-22	5.48	5.12	6.02	6.49	5.76	4.92	4.98	5.25	4.42	7.43
April-22	5.61	5.27	6.21	6.70	5.88	5.06	5.11	5.32	4.38	7.61
May-22	5.90	5.51	6.17	5.87	6.27	4.69	4.36	5.36	4.21	7.38
June-22	5.54	5.45	6.78	7.61	5.69	4.97	4.93	5.23	4.33	6.69
July-22	5.95	5.95	7.12	7.98	6.48	5.12	4.86	6.00	4.07	7.12
August-22	5.63	5.49	6.94	6.12	5.84	4.42	4.17	4.73	4.07	7.36
September-22	5.77	5.61	6.33	6.04	6.20	4.50	4.30	4.84	4.21	7.51
November-22	5.48	5.49	6.19	5.97	5.62	4.09	4.12	4.96	3.87	7.36
December-22	5.68	NM	NM	6.80	5.60	5.05	5.49	4.92	4.40	7.89
January-23	5.50	NM	NM	6.52	5.94	4.60	4.95	5.26	4.18	7.72
February-23	5.81	NM	NM	6.33	5.99	4.83	4.99	5.36	4.22	7.65
March-23	5.54	NM	NM	6.40	5.97	4.98	5.13	5.42	4.65	7.38
April-23	5.65	NM	NM	6.53	6.06	5.04	5.16	5.50	4.46	7.42
June-23	5.06	NM	NM	6.04	5.60	4.39	4.11	4.32	3.64	6.57
August-23	4.67	NM	NM	5.93	5.24	3.38	2.56	4.94	3.21	6.25
September-23	5.66	NM	NM	6.60	6.01	3.49	2.53	5.15	3.72	7.27
October-23	5.64	NM	NM	6.57	5.77	4.01	3.78	5.19	3.84	7.42
November-23	5.46	NM	NM	6.42	5.56	4.32	4.37	5.11	3.84	7.33
December-23	5.53	5.38	6.23	6.47	5.74	4.57	4.66	5.32	3.94	7.33
December-23	5.57	5.40	6.25	6.50	5.73	4.65	4.74	5.33	3.99	7.38
January-24	5.49	5.35	6.28	6.44	5.77	4.88	4.96	5.38	4.07	7.35
February-24	5.59	5.44	6.25	6.51	5.84	4.96	5.10	5.50	4.13	7.39

NOTE: Monitoring wells MW-02 & MW-03 were tampered with by an unknown person and plugged with a grout around December 2022. Monitoring wells were re-drilled in December 2023.