

M-1980-249 Houchin Gravel Pit Post Inspection Map

Stellite imagery from 10/6/2019
GPS points collected 12/14/2022

Legend

- GPS
- GPS Marker
- M-80-249 2019 Comm/Industrial Area (1 Ac)
- M-80-249 Corner - SW
- M-80-249 GPS Boundary
- M-80-249 Sloped Disturbed Area (2019 - 2.1 Ac.)
- Natural or Pre-Existing Disturbance

Bench for planting trees

Sloped areas top soiled and planted as to plan

Commercial
Industrial Area

1-2 Acre Approx.
Commercial Use

2-1 Slope

Reclaimed and
Wildlife Habitat

2-1 Slope

Wildlife Habitat

Flat Area

Approx
250 ft x
25 ft
Vegetated
and
Wildlife
Habitat

3-1 Slope

Reclaimed and
Wildlife Habitat

3-1 Slope

Top Soil

Top Soil



STATE OF
COLORADO

Ridley - DNR, Hunter <hunter.ridley@state.co.us>

Houchin Gravel Pit, M-1980-249, TR2 & SO1

Curt Houchin <curthouchin@gmail.com>

Mon, Mar 25, 2024 at 7:37 PM

To: "Ridley - DNR, Hunter" <hunter.ridley@state.co.us>

Hunter,

As per our conversation of 3/25/24, the current grading of the bench and highwall (not a highwall but a 2-1 slope) is complete; it is ready for topsoil and final grade when reclamation begins.

The approximate width of the bench is 25 + or - feet.; approximate length of bench is 250 feet.

Curt Houchin

3/25/24

[Quoted text hidden]