



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

May 14, 2024

Daniel Takami
Grand Island Resources LLC
12567 West Cedar Dr.
Lakewood, CO 80228

Re: Letter of Monitoring Compliance, First Quarter 2024 Groundwater, Effluent and Surface Water Monitoring Report; Cross Gold Mine, Permit No. M-1977-410

Dear Mr. Takami:

On April 30, 2024, the Division of Reclamation, Mining and Safety (Division/DRMS) received the First Quarter 2024 Groundwater, Effluent, and Surface Water Monitoring Report for the Cross Gold Mine, permit no. M-1977-410. At this time the Division has no comments on the report.

Please note that monitoring data is to be submitted quarterly in accordance with commitments made in TR-10.

If you need additional information or have any questions, please contact me by telephone at **303-866-3567 x8114**, or by email at patrick.lennberg@state.co.us.

Sincerely,

Patrick Lennberg
Environmental Protection Specialist

cc: Jared Ebert, DRMS

ec: Daniel Takami, Grand Island Resources LLC, danieltakami@gmail.com

