



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

June 26, 2024

SENT VIA EMAIL

Mr. Patrick Lennberg
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining, and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedance June 26, 2024

Dear Mr. Lennberg,

In accordance with Rule 3, Section 3.1.7 (9) of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining, and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected second quarter 2024 groundwater compliance samples from monitoring well CRMW-5B on April 30, 2024.

Upon review of received analytical reports, CC&V determined the groundwater sample collected at monitoring well CRMW-5B exceeded the established Numeric Protection Levels for total fluoride. Per Rule 3, Section 3.1.7 (9), this notification was due to the Division May 22, 2022, and the delay in distribution was an oversight by CC&V.

Table 1 below lists these exceedances by the location and the associated parameter. The graphs contained in Attachment 1 demonstrate the parameter trend for the collected data.

Table 1: Parameter Values

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Value Standard (mg/L)
CRMW-5B	4/30/2024	Fluoride - Total	2.75	2	2

Should you require further information please do not hesitate to contact Joshua Adams at 719.323.0438 or Joshua.Adams@Newmont.com, or me at 719.851.4048 or Katie.Blake@Newmont.com

Sincerely,

DocuSigned by:

5A3D013B629844B...
Katie Blake



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

Sustainability & External Relations Manager
Cripple Creek and Victor Gold Mining Company

EC: E. Russell
P. Lennberg
Z. Trujillo
K. Blake
J. Gonzalez
P. Barela
A. Matarrese
J. Adams



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

Attachment 1

