

July 2, 2024

Jennifer Kleatsch CDOT 222 6th St Grand Junction, CO 81501

RE: North of Douglas Pass, Permit No. M-1981-043, Inspection Problem Abated

Dear Ms. Kleatsch:

On October 24, 2023 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs & Markers was cited as a problem for failing to properly delineate the permit boundary. Corrective actions required you place boundary markers and provide photo documentation of such by the corrective action date.

On July 2, 2024 the Division received photos of the placed boundary markers. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me.

Sincerely,

Amy Geldell

Amy Yeldell Environmental Protection Specialist

EC: Travis Marshall, Senior EPS, DRMS

