



STATE OF
COLORADO

Wein - DNR, Clayton <clayton.wein@state.co.us>

New Horizon Mine, C-1981-008, 1st Quarter DMRs Review Letter

1 message

Wein - DNR, Clayton <clayton.wein@state.co.us>

Tue, Aug 6, 2024 at 2:35 PM

To: "Tennyson, Tony (Colowyo)" <tony.tennyson@tristategt.org>

Good afternoon Tony,

Attached is the Division's review letter for the New Horizon Mine's 1st Quarter Discharge Monitoring Reports. Please feel free to contact me if you have any questions or concerns.

Sincerely,
Clayton Wein
Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 720.762.6156 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
clayton.wein@state.co.us | <https://www.drms.colorado.gov>



New Horizon Mine, C-1981-008, 1st Quarter 2024 DMRs Review Letter.pdf

383K



August 6, 2024

Tony Tennyson
Elk Ridge Mining and
Reclamation, LLC
P.O. Box 628
27646 West 5th Avenue
Nucla, CO 81424

**RE: New Horizon Mine, Permit No. C-1981-008
1st Quarter 2024 Discharge Monitoring Reports Review**

Dear Tony,

The Colorado Division of Reclamation, Mining and Safety (the Division) has finished reviewing the 2024 1st Quarter Discharge Monitoring Reports (DMRs). The reports were received on February 28, 2024 (January Report), March 22, 2024 (February Report), and April 30, 2024 (March and quarterly Report). The Division finds the reports to be in compliance with the following Rules:

- **Rule 4.05.13(2)(i)** – Samples are measured accurately and record the quality and quantity of the water discharged from the permit area.
- **Rule 4.05.13(2)(ii)** – Discharge occurred from 013-A in January, February and March of 2024. Parameters tested were within acceptable value ranges, except for one WET Testing value. WET Testing for the reproduction of Ceriodaphnia failed during the 1st quarter. The Operator is working with the Division and the Water Quality Control Division and will submit a future Technical Revision to address this issue. Outfalls 12-A and 016-A did not discharge during the quarter; therefore, no exceedances occurred at these monitoring locations
- **Rule 4.05.13(2)(iii)** – Discharge Monitoring Reports are received on a quarterly basis and filed with the Division within 90 days of the sample collection.

This concludes the Division's review of the 2024 1st Quarter Discharge Monitoring Reports. If you have any questions, please contact me at (720)-762-6156.



Sincerely,

A handwritten signature in black ink that reads "Clayton Wein". The script is cursive and fluid, with the first name "Clayton" and last name "Wein" clearly distinguishable.

Clayton Wein
Environmental Protection Specialist
clayton.wein@state.co.us

cc: Travis Marshall, Senior Environmental Protection Specialist GJFO