

August 9, 2024

Franchesca Mallonee Four Corners Materials 9755 CR 213 Durango, CO 81303

## Simmons Pit, Permit No. M-2009-024, Inspection Problem Abated

Dear Ms. Mallonee:

On June 11, 2024 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs and markers was cited as a problem for not having a posted mine sign at the entrance. Corrective actions required you to submit photo documentation that a sign had been posted by the corrective action date.

On August 6, 2024 the Division received photos of the corrected mine signs via email. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me.

Sincerely,

ald core

**Todd Jesse** Environmental Protection Specialist

EC: Travis Marshall, Senior EPS, DRMS





**T** +1 (970) 247-2172 **F** +1 (970) 259-3631

www.fourcornersmaterials.com

August 6, 2024

Colorado Div of Reclamation, Mining and Safety 1313 Sherman St. Denver, CO 80203 Attn: Todd Jesse Todd.Jesse@state.co.us

RE: Mud Creek and Simmons Pit Inspections June 11, 2024

Dear Mr. Jesse

This letter responds to necessary corrective actions stated during the June 11, 2024 inspections of our Simmons and Mud Creek sites near Mancos, CO

## Simmons

It was discovered at our Simmons Pit that the sign had fallen down (see below)



PERMIT #: M-2009-024 INSPECTOR'S INITIALS: TJ1 INSPECTION DATE: June 11, 2024

Photo 5: View to the northeast of fallen sign at the entrance to the site.

Four Corners has since ordered a new sign with upgraded materials including steel square tubing to



**T** +1 (970) 247-2172 **F** +1 (970) 259-3631

www.fourcornersmaterials.com

better withstand the winds near the pit. The new sign was placed approximately July 29, 2024. (See below)



Corrective Action photo with new sign

## **Mud Creek**

At our Mud Creek site, an area of exposed groundwater was discovered and an exposed groundwater permit was not found. (See below)



**T** +1 (970) 247-2172 **F** +1 (970) 259-3631

www.fourcornersmaterials.com

PERMIT #: M-2008-010 INSPECTOR'S INITIALS: TJ1 INSPECTION DATE: June 11, 2024

## **PHOTOGRAPHS**



Photo 1: View to the west of exposed groundwater at bottom of pit.

Four Corners has recently covered this area with at least 4 inches of existing soil and groundwater is no longer exposed. (See below)



**T** +1 (970) 247-2172 **F** +1 (970) 259-3631

www.fourcornersmaterials.com



Photo of groundwater covered approximately July 10, 2024.

Thank you for the opportunity to provide this information. Please let me know if you have any questions.

Yours sincerely

-Man-

Franchesca Mallonee Four Corners Materials Environmental Specialist franchesca.mallonee@fourcornersmaterials.com