

Gibson - DNR, Amber <amber.gibson@state.co.us>

Waste Inspection Report Problem

Gibson - DNR, Amber <amber.gibson@state.co.us>

Tue, Oct 8, 2024 at 12:33 PM

To: jterry@newelkcoal.com, john terry <jterry316314@gmail.com>, Frank Kirby <fkirby0428@gmail.com>

Hi John,

Can you please send me a new certification page for the waste inspection report?

Certification

This inspection was conducted by John Terry, a qualified professional and MSHA certified inspector of earth and rock-fill embankments, waste banks and impoundments, under the direction a registered professional engineer licensed in the State of Colorado.

This is to certify, to the best of my knowledge and belief, that maintenance, since the previous certification and as determined during this inspection and discussions with mine personnel, is in accordance with designs as approved by the Division of Reclamation, Mining and Safety.

Inspector Date Professional Engineer Date

Inspections completed in compliance with Rule 4.09.1(11)(b) must be submitted to the Division within two weeks of completion

Thanks,

Amber M. Gibson Environmental Protection Specialist I



P 720.836.0967 | F 303.832.8106 | amber.gibson@state.co.us

Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 Physical: 1313 Sherman Street, Room 215, Denver, CO 80203

https://drms.colorado.gov/