



November 27, 2024

Jared Graff
J Graff Enterprises, LLC
6454 Graff Road
Delta, CO 81416

**Re: Best Rock Sand & Gravel Pit 1, Permit M-2019-018,
Receipt of Corrective Action Documentation**

Dear Mr. Graff:

The Division received a response to a Compliance Problem cited in the Division's report from the inspection that was conducted on November 14, 2024. The status of the corrective action in regard to the cited problem is as follows.

Compliance Problem, Hydrologic Balance: The operator has provided insufficient documentation related to water rights and well permitting.

This problem is resolved as a result of documentation emailed by the Division of Water Resources (DWR) to the Division on November 27, 2024. This documentation is an email from Scott King (District 41 and 62 Water Commissioner) stating that you have been proactive in engaging with DWR regarding water rights at your site. Mr. King also stated that DWR has no concerns regarding this site and compliance with water well permitting or water rights issues.

If you have any questions, please contact me at Rob.Zuber@state.co.us or by calling (720) 601-2276.

Thank you,

Robert D. Zuber, P.E.
Environmental Protection Specialist

Cc: Amy Eschberger, DRMS

