

PHOTOGRAPHS



Photo 1: Looking west from the pit entrance road, across the south highwall.



Photo 2: Looking south at the south highwall. The access road to the pit and east highwall are in the left portion of the photo.



Photo 3: Looking east at a product stockpile.




Photo 4: Looking west at stockpiled material.



Photo 5: Standing at the northeast corner of the permit, looking southwest across the pit.




Photo 6: Looking north along the east highwall. The arrow points to the reclaimed northern slopes.



Photo 7: Looking east along a reclaimed northern slope. The white marker indicates the northeast corner of the permit boundary. The fence line in the photo lines the eastern perimeter.




Photo 8: Looking west the fence lines the western permit perimeter.




Photo 9: Mine sign posted at the entrance to the permit boundary.



Photo 10: Looking north along the vegetated topsoil pile located to the south of the southern pit boundary.