

# WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME: 12/17/24

INSPECTOR: Michael Howard

INSPECTOR TITLE: Environmental Tech

This inspection was conducted to comply with DMG Rule 4.09.1(11).

This inspection was conducted to evaluate:

X A. Stability of fill (quarterly inspection)

\_\_\_\_\_B. Critical construction periods:

\_\_\_\_1. Removal of all organic material/topsoil

## \_\_\_\_2. Placement of underdrainage system

### \_\_\_\_\_3. Installation of surface drainage system

#### \_\_\_\_\_4. Placement and compaction of fill materials

## \_\_\_\_5. Revegetation

NOTES: Light snow on the ground. Fill is stable. Very little erosion is present.

This image shows a single sheet of white paper with horizontal blue or grey ruling lines, typical of notebook paper. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.