

February 27, 2025

Tim Loncarich CW Construction, LLC 825 21 ½ Rd Grand Junction, CO 81505

## RE: Gunnison River Gravel Pits, Permit No. M-2009-048, Inspection Problem Abated

Dear Mr. Loncarich:

On February 12, 2025 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs & Markers was cited as a problem for failing post a mine sign permit boundary entrance. Corrective actions required you place a sign and provide photo documentation of such by the corrective action date.

On February 27, 2025 the Division received photos of the placed boundary markers. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me.

Sincerely,

Amy Geldell

**Amy Yeldell** Environmental Protection Specialist

EC: Travis Marshall, Senior EPS, DRMS

