


Annual Report 2023

Hummingbird Mine
DRMS Permit File M-2019-057
USFS 2810-021210-MPO-2019-003



Mining Area 1:

No activity took place in mining area 1.

Mining Area 2:

No Activity took place in mining area 2.

Mining Area 3:

New Disturbance:

- Hole 14 (Lat 39° 1.583'N Long 105° 20.712'W) - 50 sq/ft +/-
- Hole 20 (Lat 39° 1.598'N Long 105° 20.604'W) - 150 sq/ft +/-
- Hole 25 (Lat 39° 1.573'N Long 105° 20.629'W) - 50 sq/ft +/-

Reclamation work:

- Hole 20 (Lat 39° 1.598'N Long 105° 20.604'W) - 150 sq/ft +/-

Noxious weed management was done in the way of 20 plants +/- of Common Mullein (*Verbascum Thapsus*) being pulled by hand or dug out with a shovel in mining area number 3 where indicated on the map.

Total New Disturbance - 250 sq/ ft +/- (or 0.01 acres)

Total reclamation - 150 sq/ft +/-

Noxious Weeds - 20 plants +/- pulled