

**Logan Wash Mine Annual Report**  
**Permit No. M-1977-424**

**Reference Table for Figures 4A and 4B.**

| <b>Area Number<br/>(Exhibit E &amp; F)</b> | <b>Name</b>                      | <b>Warranty<br/>Release<br/>(acres/year)</b> |
|--------------------------------------------|----------------------------------|----------------------------------------------|
| 1                                          | Mine Dump <sup>a</sup>           | 13.36/2022                                   |
| 2                                          | Upper Mine Bench                 | 0.74/2022                                    |
| 3                                          | Lower Mine Bench                 | Not reclaimed                                |
| 4                                          | Research Mine Bench<br>/ Dump    | 4.26/2022                                    |
| 5                                          | Old Surface Process<br>Facility  | 1.82/1986                                    |
| 6                                          | Two Overflow Ponds               | 2.86/2006                                    |
| 7                                          | Equipment & Parts<br>Storage     | 0.67/1986                                    |
| 8                                          | Ventilation Fan Site             | 0.41/2006                                    |
| 9                                          | Power Substation                 | 0.75/2006                                    |
| 10                                         | Helo Pad                         | 0.24/2022                                    |
| 11                                         | Guard Gate Area                  | Removed<br>2022                              |
| 12                                         | Met Tower                        | 0.80/2006                                    |
| 13                                         | Misc. Access Roads <sup>e</sup>  | 8.12/1986                                    |
| 14                                         | Oil Transfer Pipeline            | 0.5/2006                                     |
| 15                                         | Heater/Treater                   | 2.96/2006                                    |
| 16                                         | Microwave Tower                  | 0.11/2006                                    |
| 17                                         | Exhaust Stack                    | 3.00/2006                                    |
| 18                                         | Logan Wash Road                  | Removed<br>2022                              |
| 19                                         | Surface Process<br>Control       | 1.0/2006                                     |
| 20                                         | Top Soil Storage                 | 0.5/2006                                     |
| 21                                         | Berm Material                    | 0.33/1986                                    |
| 22                                         | Heater Treater<br>Meteorological | 0.18./1986                                   |
| B1-B10                                     | Logan Wash Road<br>Realign       | ~5.0/1986 &<br>2022                          |
| New                                        | Soil Barrow Area<br>(2005)       | 0.65/2006                                    |
| 23                                         | Evaporation Pond and<br>Pipeline | Not<br>reclaimed                             |
| Total                                      |                                  | 48.26 <sup>g</sup>                           |