ANNUAL & QUARTERLY POND INSPECTION

COORS ENERGY COMPANY

KEENESBURG MINE SITE

	KEENESBURG	J MIINE SILE	
Date of Inspection 3/5/2025			
Pond Identification:	Sediment Pond #2	Dugout	
Type of Pond	Sediment	Permanent	
Capacities	15.6 acre ft. 5,097,925 gals.	19.7 acre ft. 6,437,760 gals.	
Approx. water level - (% of capacity)	Trace	Trace	
Sediment level -			
(% of capacity)	0	0	
Out flow			
Erosional Features	yes - no	yes - no	
Rills / Gullies	No	No	
Inadequate			
Vegetation	No	No	
Outlet Channel			
Erosion	No	No	
Burrows	No	No	
Other	NA	NA	
Structural Issues			
Settlement	No	No	
Cracks/Slides	No	No	
Seepage	None	None	
Spillways (cond.)	Good	Good	
Other	NA	NA	

Signature (P.E. or Authorized Inspector): Ben Moline, PE

Moline