



A CRH COMPANY



A CRH COMPANY

2273 River Road  
PO Box 3609  
Grand Junction, CO 81502  
(970) 243-4900

3794 County Road 109  
Glenwood Springs, CO 81601  
(970) 704-4800

13124 6175 Road  
Montrose, CO 81403  
(970) 249-1815

964 CR 63L  
Telluride, CO 81435  
(970) 728-3775

[www.united-gj.com](http://www.united-gj.com)

April 30, 2025

Division of Reclamation, Mining and Safety  
1313 Sherman Street, Room 215  
Denver, CO 80203

Attn: Brock Bowles

RE: M-2001-023 – Topsoil Stockpiles & Signage Corrective Action

Dear Brock,

During our site inspection on November 20, 2024, you noted a potential violation regarding the storage of overburden next to a topsoil pile. This issue has been addressed by removing the overburden material to ensure it does not come into contact with the topsoil. Furthermore, we have installed signage clearly indicating that the topsoil should not be disturbed or used for any purposes other than reclamation. Please refer to the attached pictures of the signs and the improved stockpile.

If you have any questions or require additional information, please feel free to reach out.

Sincerely,

Tyra Bartuska  
CO-NM Group Environmental Manager  
Oldcastle SW Group, Inc.  
[tyra.bartuska@unitedco.com](mailto:tyra.bartuska@unitedco.com)

Enclosure:

Signs & Improved Stockpile Photos





TOP SOIL  
DO NOT USE





TOP SOIL  
DO NOT USE



