

Simmons - DNR, Leigh <leigh.simmons@state.co.us>

## C1981022, Elk Creek Mine, April Inspection Report

**Simmons - DNR, Leigh** <leigh.simmons@state.co.us> To: Doug Smith <Doug.Smith@oxbow.com>

Fri, May 2, 2025 at 4:15 PM

#### Attached

Leigh Simmons Environmental Protection Specialist



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

P 720.220.1180

1313 Sherman Street, Room 215, Denver, CO 80203 leigh.simmons@state.co.us | https://drms.colorado.gov



INSP-REPORTC\_C1981022\_LDS\_05022025040253.pdf 4081K



## **PERMIT INFORMATION**

Permit Number: C-1981-022	County: Delta, Gunnison	
Mine Name: Elk Creek Mine	Operation Type: Underground	
<b>Operator:</b> Oxbow Mining, LLC	Permit Status: Active	
Operator Address:	Ownership: Private	
Mr Doug Smith		
3737 Hwy 133	Operator Representative Present:	
P. O. Box 535		
Somerset, CO 81434	Doug Smith	
Operator Representative Signature: (Field Issuance Only)		

## **INSPECTION INFORMATION**

Inspection Start Date: April 24, 2 Inspection Start Time: 14:00 Inspection End Date: Inspection End Time:	2025		Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: Jo		Joint	Inspection Contacts:
None			
Post Inspection Agency:		Post	Inspection Contacts:
None			
Inspector(s):	Inspector's Signature: Signature Date:		
Leigh Simmons	Bli		May 2, 2025

### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection Y - Roads

N - Availability of Records N - Reclamation Success

Y - Backfill & Grading R - Revegetation

N - Excess Spoil and Dev. Waste N - Subsidence

N - Explosives
 N - Slides and Other Damage
 N - Fish & Wildlife
 N - Support Facilities On-site
 Y - Signs and Markers

Y - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Other N - Special Categories Of Mining

N - Processing Waste Y - Topsoil

### **COMMENTS**

This was a partial inspection by Leigh Simmons of the Division of Reclamation, Mining and Safety (Division). The weather was clear and dry. The status of the Elk Creek Mine is "active" however no coal is being mined and the only activity since the last inspection was site maintenance.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Spring runoff was moderate, water was flowing in Elk Creek but the flow rate was not particularly high. The reclaimed channel was stable.

### REVEGETATION – Rule 4.15

Vegetative Cover; Timing:

Weed spraying was in progress around the facilities area. The banks of the reclaimed channel were well-vegetated with excellent diversity and very few weeds observed.

#### **DOCUMENTS RECEIVED**

N/A

### **OTHER (SPECIFY)**

N/A

## ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

# **PHOTOGRAPHS**



Figure 1: Elk Creek channel, 1 of 8



Figure 2: Elk Creek channel, 2 of 8



Figure 3: Elk Creek channel, 3 of 8



Figure 4: Elk Creek channel, 4 of 8



Figure 5: Elk Creek channel, 5 of 8



Figure 6: Elk Creek channel, 6 of 8



Figure 7: Elk Creek channel, 7 of 8



Figure 8: Elk Creek channel, 8 of 8