

2720 Ruby Vista Drive
Suite 101
Elko, Nevada 89801
775.777.8003
www.Linkan.com

To:
Department of Natural Resources
Division of Reclamation, Mining and Safety

Attention: **Peter Hays**
Re: **Schwartzwalder WTP**
Job Number: **25-US-0221**

Field Service Report

Site: Schwartzwalder Mine	Location: Golden, CO
Site Contact: Peter Hays	Date: 05/19/2025
Service Request Description: Transition at Startup / Plant Commissioning	

Description of Service

- Measured MW-18: 161.4 ft
- Measured Jeffery Mine Shaft: 114.1 ft
- Kessler Reclamation onsite for Jim Harrington's equipment.
- Calibrated Rad Instruments.

Equipment Used:	
	Signature <i>Bryant Acevedo</i>







Schwartzwalder Field Service Report 5/19/25

1 message

Bryant Acevedo <bryant.acevedo@linkan.com>

Mon, May 19, 2025 at 3:46 PM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

Good afternoon,

Please see attached for today's field service report. Including pictures of the empty areas where the equipment was taken from site .

Best,

Bryant Acevedo
Operator Technician



cell: 720-238-6169

linkan.com • bryant.acevedo@linkan.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information.

Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

3 attachments



IMG_7400.jpeg
1676K



IMG_7399.jpeg
1462K



Field Service Report 05.19.25.pdf
333K