



Schwartzwalder Daily Summary Report



Report Date:	5/30/2025	Lead Operator:	Bryant A
		Assistant Operator(s):	

Effluent Discharged:	0.000 Mgal	MW-18 Level:	151 ft
Average Flowrate:	0 gpm	Transducer Level:	109 ft
Effluent to Date:	0.000 Mgal		



Safety Issues/Concerns:
 - N/A

Notes:

- Patrick Delanye onsite.
- Removed broken valve on the plant influent line, installed a new flange with new gasket and bolts.
- Installed StarLinx Control Monitoring System.
- Item B30 completed. Repaired PVC leak on intake sample port valve.
- Continued to work on the anti scale pumps wiring and ORP sensor wiring.
- Fixed drain valve on IX intake.
- Installed Cartridge Filters for RO #1.
- Graphs for Flow and pH Do not have data as the PLC's are offline due to the StrideLinx remote monitoring control system work.



Schwartzwalder Daily Summary Report 5/30/25

2 messages

Bryant Acevedo <bryant.acevedo@linkan.com>

Fri, May 30, 2025 at 2:16 PM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

Good afternoon,

See attached for today's summary report and pictures of the anti scale pumps plumbed and wired , as well as the ORP sensor wired.

Best,

Bryant Acevedo
Operator Technician



cell: 720-238-6169

linkan.com • bryant.acevedo@linkan.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information.

Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

5 attachments



IMG_7510.jpeg
2522K



IMG_7511.jpeg
2376K



IMG_7509.jpeg
2351K



IMG_7508.jpeg
2463K



SWTP Daily Summary Report 5.30.25.pdf
205K

Bryant Acevedo <bryant.acevedo@linkan.com>

Fri, May 30, 2025 at 2:18 PM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

See attached for pictures of

Before and After for Item B30 completed.

Side by Side old and new IX intake drain valve.

New Cartridge filters for RO#1.

New Plant Influent Flange.

Get [Outlook for iOS](#)

From: Bryant Acevedo <bryant.acevedo@linkan.com>

Sent: Friday, May 30, 2025 2:16:11 PM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>; Sam Billin <sam.billin@linkan.com>; Quinn Westmoreland <quinn.westmoreland@linkan.com>; Brandy Wadford <brandy.wadford@linkan.com>; Jared Buck <jared.buck@linkan.com>; Alex Schwiebert <alex.schwiebert@linkan.com>; Chris Prosper <chris.prosper@linkan.com>; Patrick Delaney <pdelaney@blackfoxmining.com>

Subject: Schwartzwalder Daily Summary Report 5/30/25

[Quoted text hidden]

6 attachments



IMG_7504.jpeg
598K



IMG_7512.jpeg
592K



IMG_7506.jpeg
953K



IMG_7507.jpeg
2989K



IMG_7505.jpeg
558K



IMG_7982.jpeg
1965K















