




# Schwartzwalder Daily Summary Report



|              |          |                        |           |
|--------------|----------|------------------------|-----------|
| Report Date: | 6/4/2025 | Lead Operator:         | Patrick D |
|              |          | Assistant Operator(s): | Bryant A  |

|                      |            |                   |        |
|----------------------|------------|-------------------|--------|
| Effluent Discharged: | 0.000 Mgal | MW-18 Level:      | 147 ft |
| Average Flowrate:    | 0 gpm      | Transducer Level: | 96 ft  |
| Effluent to Date:    | 0.000 Mgal |                   |        |



| Finished Water Quality |      |    |      |
|------------------------|------|----|------|
| Parameters             | Temp | pH | Cond |
| Values                 | NA   | NA | NA   |

| Chemical Inventory |             |         |         |
|--------------------|-------------|---------|---------|
| Chemicals          | Antiscalant | NaOH    | BaCl    |
| Vol. Used          | NA          | NA      | NA      |
| Vol. Remaining     | NA          | NA      | NA      |
| Vol. Staged        | 5500 Gal    | 644 Gal | 325 Gal |
| Days Available     | #VALUE!     | #VALUE! | #VALUE! |

## Safety Issues/Concerns:

- N/A

## Notes:

- Patrick Delaney onsite.
- Peter Hyas onsite.
- Contractor onsite to fix Garage door getting stuck not opening all the way. Garage door has been fixed.
- Installed Drain between RO's and IX vessel's.
- Batched Barium Chloride.
- Recirculated water from Mine Pump back underground. Checked for leaks. NO leaks.
- Filled RO #1 and bled perservatives from winterization.
- Prepped for Starting the system tomorrow morning.



---

## Schwartzwalder Daily Summary Report 6/4/25

1 message

---

**Bryant Acevedo** <bryant.acevedo@linkan.com>

Wed, Jun 4, 2025 at 3:18 PM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

Good afternoon,

See attached for today's summary report and a picture of the new drain valve installed between the RO's and IX Vessel's.

Best,

**Bryant Acevedo**  
*Operator Technician*



cell: 720-238-6169

[linkan.com](http://linkan.com) • [bryant.acevedo@linkan.com](mailto:bryant.acevedo@linkan.com)

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information.

Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

---

### 2 attachments



IMG\_7558.jpeg  
1109K



SWTP Daily Summary Report 6.4.25.pdf  
231K



