



Schwartzwalder Daily Summary Report



Report Date:	6/2/2025	Lead Operator:	Patrick D
		Assistant Operator(s):	Bryant A

Effluent Discharged:	0.000 Mgal	MW-18 Level:	148 ft
Average Flowrate:	0 gpm	Transducer Level:	99 ft
Effluent to Date:	0.000 Mgal		



Safety Issues/Concerns:
 - N/A

Notes:

- Patrick Delaney onsite.
- RSO Patrick Hendrickson onsite.
- Item B31 Completed. Installed Sample Port between the RO and IX System.
- Item B29.2 Completed. Added Drain Vlve in the IX Systemt Discharge PVC Line for Winterization.
- Continued woriking on Item B36 -Installation of ORP Sensor at Inlfuent Pipe.
- Finished wiring the Anti-Scale pumps. Ready to be programmed and tested.
- Walchem is having issues receiving Data, Graphs will not be shwoing trends.



Schwartzwalder Daily Summary Report 6/2/25

1 message

Bryant Acevedo <bryant.acevedo@linkan.com>

Mon, Jun 2, 2025 at 2:37 PM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

Good afternoon,

See attached for today's summary report and pictures of

- Item B31 completed. Installed sample port between RO and IX circuit.
- Item B29.2 completed. Added drain valve in the IX system discharge PVC line for winterization.
- Item B36. Continued work on the ORP sensor.

Best,

Bryant Acevedo

Operator Technician



cell: 720-238-6169

linkan.com • bryant.acevedo@linkan.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information.

Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

7 attachments



IMG_7522.jpeg
1729K



IMG_7523.jpeg
1900K



IMG_7525.jpeg
2413K



IMG_7524.jpeg
2048K



IMG_7526.jpeg
1049K



IMG_7527.jpeg
3061K

 **SWTP Daily Summary Report 6.2.25.pdf**
203K






ASHRAV LEAD
*14C1B-00112
V2ALVUE58025
1.6MPa (230psi) NPT
24C10108-H NSE-61

150-01 PVC1
205 PSI

SPEARED
UNION
4\"/>

Model No. _____
OWNER'S I.D. NO. _____
REMARKS _____
Dry and Wet Check: all Pass _____
Temperature/Sinking Service Date _____
Year Manufactured _____
Date Installed _____
MONTHLY INSPECTION TABLE
DATE _____





CLOSE ASAHI AV VALVE OPEN
MADE IN JAPAN

